UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.	
10/667,604	09/23/2003	Maurice Caldwell	1875.4670000	9747	
	7590 03/18/200 SLER, GOLDSTEIN &	EXAMINER			
1100 NEW YO	RK AVENUE, N.W.	MILLS, DONALD L			
WASHINGTO	N, DC 20005		ART UNIT	PAPER NUMBER	
			2416		
			MAIL DATE	DELIVERY MODE	
			03/18/2009	PAPER	

Please find below and/or attached an Office communication concerning this application or proceeding.

The time period for reply, if any, is set in the attached communication.

Office Action Summany		Application No.		Applicant(s)				
		10/667,604		CALDWELL ET AL.				
Office Action Summary			Examiner		Art Unit			
			DONALD L. I		2416			
Period fo	The MAILING DATE of this commur or Reply	nication appe	ears on the co	over sheet with the o	correspondence ad	ddress		
A SHORTENED STATUTORY PERIOD FOR REPLY IS SET TO EXPIRE 3 MONTH(S) OR THIRTY (30) DAYS, WHICHEVER IS LONGER, FROM THE MAILING DATE OF THIS COMMUNICATION.  - Extensions of time may be available under the provisions of 37 CFR 1.136(a). In no event, however, may a reply be timely filed after SIX (6) MONTHS from the mailing date of this communication.  - If NO period for reply is specified above, the maximum statutory period will apply and will expire SIX (6) MONTHS from the mailing date of this communication.  - Failure to reply within the set or extended period for reply will, by statute, cause the application to become ABANDONED (35 U.S.C. § 133). Any reply received by the Office later than three months after the mailing date of this communication, even if timely filed, may reduce any earned patent term adjustment. See 37 CFR 1.704(b).								
Status								
1)[🔀	Responsive to communication(s) file	ed on 23 Ser	ntember 200	13				
·		2b)⊠ This a						
<i>'</i> —		<i>,</i> —			secution as to the	e merits is		
٥/١	Since this application is in condition for allowance except for formal matters, prosecution as to the merits is closed in accordance with the practice under <i>Ex parte Quayle</i> , 1935 C.D. 11, 453 O.G. 213.							
	·	ioo undor Ex	c parto Quay	,, 1000 O.B. 11, 10	00 0.0. 210.			
Dispositi	on of Claims							
4)🛛	Claim(s) 1-30 is/are pending in the	application.						
	4a) Of the above claim(s) is/are withdrawn from consideration.							
	Claim(s) is/are allowed.							
·	)⊠ Claim(s) <u>1-30</u> is/are rejected.							
· ·	Claim(s) is/are objected to.							
•	Claim(s) are subject to restrict	ction and/or	election real	uirement				
٥/١	are subject to resum	otion ana/or v	oloollon roqi	diromont.				
Applicati	on Papers							
9)🛛	The specification is objected to by th	ne Examiner.						
-	The drawing(s) filed on <u>23 Septemb</u>			epted or b)⊠ objec	ted to by the Exa	miner.		
<i>,</i> —	Applicant may not request that any obje							
				•	• •	ER 1 121(d)		
11)	Replacement drawing sheet(s) including the correction is required if the drawing(s) is objected to. See 37 CFR 1.121(d).							
11) The oath or declaration is objected to by the Examiner. Note the attached Office Action or form PTO-152.								
Priority u	ınder 35 U.S.C. § 119							
<ul> <li>12) Acknowledgment is made of a claim for foreign priority under 35 U.S.C. § 119(a)-(d) or (f).</li> <li>a) All b) Some * c) None of:</li> <li>1. Certified copies of the priority documents have been received.</li> <li>2. Certified copies of the priority documents have been received in Application No.</li> <li>3. Copies of the certified copies of the priority documents have been received in this National Stage application from the International Bureau (PCT Rule 17.2(a)).</li> <li>* See the attached detailed Office action for a list of the certified copies not received.</li> </ul>								
Attachment  1) Notic  2) Notic  3) Inforr			4) 5) 6)	Interview Summary Paper No(s)/Mail Da	(PTO-413) ate			

Application/Control Number: 10/667,604 Page 2

Art Unit: 2416

#### **DETAILED ACTION**

# **Specification**

1. The disclosure is objected to because of the following informalities: Paragraph 0002 fails to properly cite the application number of the commonly owned, copending application.

Appropriate correction is required.

# **Drawings**

2. The drawings are objected to because formal drawings are required. Corrected drawing sheets in compliance with 37 CFR 1.121(d) are required in reply to the Office action to avoid abandonment of the application. Any amended replacement drawing sheet should include all of the figures appearing on the immediate prior version of the sheet, even if only one figure is being amended. The figure or figure number of an amended drawing should not be labeled as "amended." If a drawing figure is to be canceled, the appropriate figure must be removed from the replacement sheet, and where necessary, the remaining figures must be renumbered and appropriate changes made to the brief description of the several views of the drawings for consistency. Additional replacement sheets may be necessary to show the renumbering of the remaining figures. Each drawing sheet submitted after the filing date of an application must be labeled in the top margin as either "Replacement Sheet" or "New Sheet" pursuant to 37 CFR 1.121(d). If the changes are not accepted by the examiner, the applicant will be notified and informed of any required corrective action in the next Office action. The objection to the drawings will not be held in abeyance.

Application/Control Number: 10/667,604 Page 3

Art Unit: 2416

### Claim Rejections - 35 USC § 102

3. The following is a quotation of the appropriate paragraphs of 35 U.S.C. 102 that form the basis for the rejections under this section made in this Office action:

A person shall be entitled to a patent unless –

(e) the invention was described in (1) an application for patent, published under section 122(b), by another filed in the United States before the invention by the applicant for patent or (2) a patent granted on an application for patent by another filed in the United States before the invention by the applicant for patent, except that an international application filed under the treaty defined in section 351(a) shall have the effects for purposes of this subsection of an application filed in the United States only if the international application designated the United States and was published under Article 21(2) of such treaty in the English language.

4. Claims 1-30 are rejected under 35 U.S.C. 102(e) as being anticipated by Turner (US 7,305,047 B1).

Regarding claims 1, 23, and 28, Turner discloses an automatic lane assignment for a receiver, which compromises:

Transmitting an A-ordered set from the first node; transmitting an ordered set from the first node after said transmitted A-ordered set; and receiving the ordered set at the second node; wherein: the ordered set complies with IEEE Std 802.3ae specifications for ordered sets; and the ordered set is different from ordered sets predefined by the IEEE Std 802.3ae specifications (Note: the Examiner interprets the claims as relating to lane ordering initialization. In addition, the process of ordered set verification, as claimed, is well-known as taught by Infiniband TM Architecture Release 1.0, "Chapter 5: Link/Phy Interface," Vol. 2, Physical Specifications, October 24, 2000, pp. 80-81. Turner discloses automatic lane assignment, which occurs during initialization or an operation, such as following a transmission of an A-ordered set that verifies synchronization according to the IEEE 802.3 standard. Referring to Figures 11 and 12, incoming data is received from a standard XAUI transmitter on input port 1102 as lanes A through D. The

data is then de-serialized (1104), decoded (1106), and de-skewed (1108). The de-serializing, decoding and de-skewing is similar to that which occurs in the prior art XAUI receiver (FIG. 9) as already described. The XAUI receiver 1100 also includes a lane reordering block 1110 and a lane monitor 1112. The lane monitor 1112 monitors lanes A through D as packet data is received. Based on the received packet data (which is standard packet data without special lane identification codes), the lane monitor determines the proper lane assignments for lanes A through D and controls the lane reordering block 1110 based on the lane determination. The lane reordering block 1110 reorders the lanes A through D to the appropriate lanes 0 through 3 based on control signals from the lane monitor. The appropriate lanes are then passed to the control character removal block 1114 and data is finally output on port 1116. The control character removal is similar to that which occurs in the prior art XAUI receiver. In particular, Figure 12 shows the format of fault signaling that may occur in the received packets. When a XAUI link first starts up, the XAUI transmitter sends either idle control characters on all four lanes or fault sequence ordered sets. During a fault sequence, a sequence control character 1202 appears on lane 0 at the same time that a 0x1 or 0x2 character 1204 appears on lane 3. Thus, the lane monitor 1112 identifies lanes 0 and 3 by observing this fault sequence received on the input port 1102. See column 4, lines 11-58.)

Regarding claim 2, Turner discloses *wherein the ordered set is a Q-ordered set* (Turner discloses utilizing Q-ordered sets (D code-groups, valid data code-groups, and K code-groups, valid special code-groups), which are well-known code groups as set forth in Infiniband TM Architecture Release 1.0, pp. 68-77, 80-81, for lane verification in accordance with the IEEE 802.3ae standard and Infiniband standard. See column 1, lines 12-20.)

Regarding claim 3, Turner discloses wherein a code group in a lane 3 of the Q-ordered set is one of 000000001 and 000000010 (Referring to Figure 12, when a XAUI link first starts up, the XAUI transmitter sends either idle control characters on all four lanes or fault sequence ordered sets. During a fault sequence, a sequence control character 1202 appears on lane 0 at the same time that a 0x1 or 0x2 character 1204 appears on lane 3. Thus, the lane monitor 1112 identifies lanes 0 and 3 by observing this fault sequence received on the input port 1102. See column 4, lines 48-58.)

Regarding claims 4 and 24, Turner discloses wherein the ordered set is preprogrammed within a Physical Coding Sublayer (Referring to Figure 12, when a XAUI link first starts up, the XAUI transmitter sends either idle control characters, formed by the physical coding sublayer per the standard, on all four lanes or fault sequence ordered sets. During a fault sequence, a sequence control character 1202 appears on lane 0 at the same time that a 0x1 or 0x2 character 1204 appears on lane 3. Thus, the lane monitor 1112 identifies lanes 0 and 3 by observing this fault sequence received on the input port 1102. See column 4, lines 48-58.)

Regarding claims 5 and 25, Turner discloses wherein the ordered set is capable of being programmed by a user (Referring to Figure 12, when a XAUI link first starts up, the XAUI transmitter sends either idle control characters, capable of being programmed by a user, on all four lanes or fault sequence ordered sets. During a fault sequence, a sequence control character 1202 appears on lane 0 at the same time that a 0x1 or 0x2 character 1204 appears on lane 3.

Thus, the lane monitor 1112 identifies lanes 0 and 3 by observing this fault sequence received on the input port 1102. See column 4, lines 48-58.)

Regarding claim 6, Turner discloses *storing the ordered set in a memory at a physical sublayer of the first node* (Referring to Figure 12, when a XAUI link first starts up, the XAUI transmitter sends either idle control characters, formed by the physical coding sublayer per the standard, on all four lanes or fault sequence ordered sets. During a fault sequence, a sequence control character 1202 appears on lane 0 at the same time that a 0x1 or 0x2 character 1204 appears on lane 3. Thus, the lane monitor 1112 identifies lanes 0 and 3 by observing this fault sequence received on the input port 1102. See column 4, lines 48-58.)

Regarding claims 7, 8, and 27, Turner discloses differentiating among the more than one ordered set stored in the queue in the memory; and causing a first ordered set to be transmitted before a second ordered set according to a hierarchy/wherein an ordered set from the ordered sets predefined by the IEEE 802.3ae specifications has precedence in the hierarchy over the ordered set (Referring to Figure 12, when a XAUI link first starts up, the XAUI transmitter sends idle control characters, formed and transmitted before a second ordered set in a first come first serve basis, on all four lanes or fault sequence ordered sets. During a fault sequence, a sequence control character 1202 appears on lane 0 at the same time that a 0x1 or 0x2 character 1204 appears on lane 3. Thus, the lane monitor 1112 identifies lanes 0 and 3 by observing this fault sequence received on the input port 1102. See column 4, lines 48-58.)

Regarding claims 9, and 16-18, Turner discloses generating the ordered set/wherein said generated ordered set is generated at a physical coding sublayer of the first node/transmitting the ordered set form the Reconciliation Sublayer to a physical coding sublayer of the first node; receiving the ordered set at the physical coding sublayer; and identifying the ordered set at the physical coding sublayer (Referring to Figure 12, when a XAUI link first starts up, the XAUI

transmitter sends either idle control characters, generated at initialization per the standard, on all four lanes or fault sequence ordered sets. During a fault sequence, a sequence control character 1202 appears on lane 0 at the same time that a 0x1 or 0x2 character 1204 appears on lane 3.

Thus, the lane monitor 1112 identifies lanes 0 and 3 by observing this fault sequence received on the input port 1102. See column 4, lines 48-58.)

Regarding claims 10-15, 29, and 30, Turner discloses wherein said generated ordered set is generated upon recognizing a link status condition/wherein said generated ordered set is generated upon recognizing a cause of the link status condition/wherein the ordered set is used to identify the cause of the link status condition/wherein said generated ordered set is generated upon detecting a link status condition/wherein said generated ordered set is generated upon detecting a cause of the link status condition/wherein the ordered set is used to identify the cause of the link status condition (Referring to Figures 11 and 12, incoming data is received from a standard XAUI transmitter on input port 1102 as lanes A through D. The data is then deserialized (1104), decoded (1106), and de-skewed (1108). The de-serializing, decoding and deskewing is similar to that which occurs in the prior art XAUI receiver (FIG. 9) as already described. The XAUI receiver 1100 also includes a lane reordering block 1110 and a lane monitor 1112. The lane monitor 1112 monitors lanes A through D as packet data is received. Based on the received packet data (which is standard packet data without special lane identification codes), the lane monitor determines the proper lane assignments for lanes A through D and controls the lane reordering block 1110 based on the lane determination. The lane reordering block 1110 reorders the lanes A through D to the appropriate lanes 0 through 3 based on control signals from the lane monitor. The appropriate lanes are then passed to the control

character removal block 1114 and data is finally output on port 1116. The control character removal is similar to that which occurs in the prior art XAUI receiver. In particular, Figure 12 shows the format of fault signaling that may occur in the received packets. When a XAUI link first starts up, the XAUI transmitter sends either idle control characters on all four lanes or fault sequence ordered sets. During a fault sequence, a sequence control character 1202 appears on lane 0 at the same time that a 0x1 or 0x2 character 1204 appears on lane 3. Thus, the lane monitor 1112 identifies lanes 0 and 3 by observing this fault sequence received on the input port 1102. See column 4, lines 11-58. Referring to Figures 18 and 19, when the lane monitor recognizes that lanes 1 and 2 are swapped the lanes are reordered accordingly, which correspondingly may happen after initialization during an idle period. See column 5, lines 30-39.)

Regarding claims 18 and 26, Turner discloses *identifying an ordered set form the ordered sets predefined by the IEEE 802.3ae specification at the physical coding sublayer* (Referring to Figure 12, when a XAUI link first starts up, the XAUI transmitter sends either idle control characters, identified by the physical coding sublayer per the standard, on all four lanes or fault sequence ordered sets. During a fault sequence, a sequence control character 1202 appears on lane 0 at the same time that a 0x1 or 0x2 character 1204 appears on lane 3. Thus, the lane monitor 1112 identifies lanes 0 and 3 by observing this fault sequence received on the input port 1102. See column 4, lines 48-58.)

Regarding claims 19-21, Turner discloses *identifying the ordered set at the second node* (Referring to Figure 12, when a XAUI link first starts up, the XAUI transmitter sends either idle control characters, identified by the physical coding sublayer per the standard, on all four lanes

or fault sequence ordered sets. During a fault sequence, a sequence control character 1202 appears on lane 0 at the same time that a 0x1 or 0x2 character 1204 appears on lane 3. Thus, the lane monitor 1112 identifies lanes 0 and 3 by observing this fault sequence received on the input port 1102. See column 4, lines 48-58.)

Regarding claim 21, Turner discloses receiving, at the third transceiver, the ordered set from the first node; transmitting, from the third transceiver, the ordered set to the second node; wherein the third node is incapable of identifying the ordered set (Referring to Figures 11-13, the XAUI receiver may be used to link integrated circuits, such as additional transceivers, or may allow the use of a cable with arbitrarily connected lanes to link system components. See column 8, lines 32-34.)

#### Conclusion

5. Any inquiry concerning this communication or earlier communications from the examiner should be directed to DONALD L. MILLS whose telephone number is (571)272-3094. The examiner can normally be reached on 9:00 AM to 5:00 PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Chi Pham can be reached on 571-272-3179. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Application/Control Number: 10/667,604 Page 10

Art Unit: 2416

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see <a href="http://pair-direct.uspto.gov">http://pair-direct.uspto.gov</a>. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

/Donald L Mills/ Examiner, Art Unit 2416 March 14, 2009